	CLASSEED ARSAGE COURSE  2337Z 12 JAN 63  CLASSEED ARSAGE  COURSE  COUR	ont-
DATE	20016 12 0411 00	D-07
то	DIRECTOR EO 12958 3.3(b) (1)>25 rs 25/9 C	
From		200
actio	OSA (1-2-3-4-5-6-7-8-9-10)  APPROVED FOR THE ACT.	321
mpo	S/C (11) DATE: AUG 2007	
	TOR: 0032Z 13 JAN 63	
70	PRITY 19150 CITE 7710	
•	OXCART	
	NO NIGHT ACTION	
	ACFT NUMBER FOUR MADE FLIGHT NUMBER THREE ON 12 JANUARY AT	
	6937 HOURS FOR ONE HOUR AND FORTY EIGHT MINUTES.	
	PILOT PARKS CO PILOT BESWICK. GROSS WEIGHT 85,000 POUNDS WITH	
	CG 21.5 PERCENT. AB TAKEOFF AND CLIMB TO 20,000 FEET. LEVELED	
	AT 20,000 FEET AND .90 MACH AND PERFORMED VARIOUS COMPARATIVE	
	COCKPIT CHECKS. ITEMS INCLUDED CONTROLS, TRIM SYSTEMS, INSTRUMENTS,	
	AIR CONDITIONING, COMMUNICATIONS SYSTEMS AS WELL AS GENERAL	
	ACCESSIBILITY AND LAYOUT. CLIMBED TO 40,000 FEET AND ACCELERATED	
	TO 1.2 MACH, DECELERATED TO .90 MACH AND APPROXIMATELY 30,000	
	FEET. ACCOMPLISHED AIR STARTS USING AFT COCKPIT IGNITION.	
	CHECKED TRIM OVERRIDE OF AFT COCKPIT OVER FORWARD COCKPIT. GEAR	
	EXTENSIONS MADE FROM AFT COCKPIT BOTH NORMAL AND EMERGENCY SYSTEMS.	
	NORMAL LANDING. BRAKE CHUTE OPERATED FROM REAR COCKPIT. CHECKED	
	NOSE GEAR STEERING AND BRAKES FROM REAR COCKPIT TAXIING IN -	
	APPEARED TO HAVE SOME DIFFICULTY IN ASSUMING CONTROL OF STEERING	
<i>)</i> · · ·	IN FORWARD COCKPIT ON ONE OF SHIFTS. PILOT HAD TROUBLE GETTING	
	SECRET Substitution	
	REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.	

7710 (IN 62284)

PAGE TWO

WARM AIR ON AUTOMATIC IN BEGINNING OF FLIGHT - CORRECTED ITSELF.

BAD STRUT LEAKAGE WAS ENCOUNTERED. STRUT LEAKS ALSO ENCOUNTERED

ON ACFT NUMBER THREE TODAY - DUE COLD WEATHER. NEXT FLIGHT

SCHEDULED FOR 15 JANUARY.

END OF MESSAGE